

9-30. Approval of Injection Well Plugging and Abandonment Plan and Prescribing Aquifer Cleanup and Monitoring (1200 TN 101 9-30)

1. AUTHORITY. To approve injection well plugging and abandonment plans and to prescribe aquifer cleanup and monitoring requirements under EPA-administered programs.

2. TO WHOM DELEGATED. Director, Water Division (WD); and Director, Enforcement and Compliance Assurance Division (ECAD).

3. LIMITATIONS. None.

4. REDELEGATION AUTHORITY.

- a. This authority may be redelegated to the branch chief level and may not be redelegated without formal amendment.
- b. An official who redelegates an authority retains the right to exercise or withdraw the authority. Redelegated authority may be exercised by any official in the chain of command down to the official to whom it has been specifically redelegated.

5. ADDITIONAL REFERENCES. 40 CFR § 144.52(a)(6); 40 CFR § 146.10.

6. SUPERSESSION. Delegation Manual, SDWA, Regional Delegation 9-30. Approval of Injection Well Plugging and Abandonment Plan and Prescribing Aquifer Cleanup and Monitoring, 1200 TN RIII 51 (January 10, 1985).

Date: APR 15 2019



Cosmo Servidio
Regional Administrator